## 411916/be

Type L # Hits		700	Search Text	DBs	Time	Comm	Error Defin ition
((38 IS&R L1 9689 or (	((3 or or	l M	85/37) or (359/566) or (430/5) or (430/321) (430/290) or (216/41) or (216/48) or (216/80) (264/1.31) or (264/1.38)).CCLS.	USPAT; US-PGPUB	2004/ 05/15 12:58		
L2 407 grating fabricat	<u>р.н</u>	grat fabr	rating with (exposure or exposing or making or abricating or fabrication).ti,ab.	USPAT; US-PGPUB	2004/ 05/15 13:00		
L3 3960 phase		phas	e adj2 (mask or masks)	USPAT; US-PGPUB	2004/ 05/15 13:02		
(phot (sub) 148638 or de or es	(ph (su or or	ユ コ	(photoresist or photoresists or resist) same (substrate or substrates or surface or surfaces or developed or developing or etched or etching or exposure or exposed or exposing)	USPAT; US-PGPUB	2004/ 05/15 13:04	••••••••••••••••••••••••••••••••••••••	
L5 1225 (1 or		(1 01	c 2) and 3 and 4	USPAT; US-PGPUB	004 5/1 3:0	••••	
L6 2536 1 and	536 1	•	l (grating or gratings).ti,ab,clm.	USPAT; US-PGPUB	2004/ 05/15 13:05		
L7 128 (2 or	(2	•	: 6) and 3	USPAT; US-PGPUB	004 5/1 3:0		
L8 2 7 and	7	•	littrow	USPAT; US-PGPUB	004 5/1 3:0		
L9 128 7 or		7 or	8	USPAT; US-PGPUB	2004/ 05/15 13:05		